

Attorney Docket No. 1837.1005

CERTIFICATE OF CORRECTION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yasuhiro ICHIHARA et al.

Application No.: 10/688,967

Confirmation No.: 4266

Filed: October 21, 2003

U.S. Patent No.: 7,004,646

Issued: February 28, 2006

Batch No.:

RECEPTACLE TYPE OPTICAL TRANSMITTER AND/OR RECEIVER MODULE

ATTENTION

BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

For:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Gene M. Garner, II

Registration No. 34,172

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,004,646

DATED: February 28, 2006

INVENTOR(S): Yasuhiro ICHIHARA et al.

Column 8, line 39, change "sockets" to -socket,--

Column 9, line 26, after "each" insert --other--

Column 10, line 23, after "board" insert --;--

Column 10, line 33, after "each" insert --other--

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,004,646

No. of add'l copies @ 50¢ per page

